

# LSR-XXX SERIES


#### Load sensor






### **Wiring Diagram**

TYPICAL WIRING DIAGRAM FOR LOAD LOSS DETECTION



TYPICAL WIRING DIAGRAM FOR OVERLOAD DETECTION



# Ordering Information

MODEL	LINE VOTAGE
LSR-24	24VAC
LSR-115	115VAC
LSR-230	230VAC

### **Description**

FX: 262-252-1616

The LSR-xxx Series load sensors use current levels to determine feed rates, tool wear, loss of prime on pumps, mixer viscosity and all types of overload and underload conditions. They may also be used to stage pump motors, chillers and other machinery. These devices combine a current transformer (CT) with Form C (SPDT) relay contacts to switch alarm circuits, contactors or any resistive or inductive load. One simple screwdriver adjustment will calibrate the sensor for all single-phase or 3-phase applications up to 100hp.

#### **Features**

- Can monitor current of motors up to 100Hp
- Fine adjustment with 20-turn pot
- Status LEDs

## **Specifications**

**Functional Characteristics** 

**Isolation** 600VAC rms

**Current Adjustment Range** 

(Typical) 2-100A

**Current Adjustment Range** 

(Min-Max) 0.5-135A

**Trip Setpoint** Adjustable to ±1% range

**Input Characteristics** 

**Control Power:** 

LSR-24 24VAC LSR-115 115VAC LSR-230 230VAC

Max Current Ratings 135A max. continuous

**Output Characteristics** 

**Output Contact Rating (SPDT):** 

Pilot Duty 480VA @ 240VAC

General Purpose 10A

**General Characteristics** 

**Temperature Range** -20° to 70°C (-4° to 158°F)

Wire Size #12-24AWG
Hole Size 0.725" diameter
Terminal Torque 7 in.-lbs.

Safety Marks

**CSA, CSA-NRTL/C** (File #46510) **CE** IEC 60947

**Dimensions H** 42.42 mm (1.67"); **W** 58.42 mm (2.3");

**D** 90.43 mm (3.56")

Weight 0.4 lb. (6.4 oz., 181.44 g)

Mounting Method Four #6 screws 3/4" in length

Caution: This product should not be relied upon solely for safety of life or safety applications.

PH: 262-252-1600